



BLS Series ID

2016 2017 2018 2019 2020 11/2021 9/2021 12/2021

CUUR0000SA0

|           |  |      |     |     |     |      |     |      |      |
|-----------|--|------|-----|-----|-----|------|-----|------|------|
| WPU80     | Construction (partial)                   | 0.9  | 2.7 | 4.5 | 3.5 | 0.9  | 0.3 | 5.6  | 11.9 |
| WPU801    | New nonresidential building construction | 0.4  | 3.1 | 5.4 | 4.0 | 1.3  | 0.3 | 7.1  | 12.5 |
| WPU801101 | New warehouse building construction      | 1.3  | 3.5 | 4.0 | 4.5 | -0.1 | 0.2 | 12.8 | 20.5 |
| WPU801102 | New school building construction         | -0.3 | 3.5 | 5.4 | 4.7 | 1.2  | 0.0 | 5.8  | 9.6  |
| WPU801103 | New office building construction         | 1.3  | 2.6 | 5.6 | 3.6 | 1.2  | 0.7 | 6.7  | 13.1 |
| WPU801104 | New industrial building construction     | 0.0  | 4.0 | 5.9 | 4.5 | 2.0  | 0.5 | 8.8  | 13.7 |
| WPU801105 | New health care building construction    | 0.1  | 2.6 | 5.0 | 3.1 | 1.4  | 0.1 | 5.4  | 10.9 |

BLS Series ID

2016 2017 2018 2019 2020 11/2021 9/2021 12/2021

|         |                                |      |     |     |     |      |      |      |      |
|---------|--------------------------------|------|-----|-----|-----|------|------|------|------|
| WPU1322 | Cement                         | 5.0  | 4.3 | 2.8 | 1.9 | 1.9  | 0.0  | -0.4 | 4.2  |
| WPU133  | Concrete products              | 3.1  | 2.9 | 3.5 | 3.1 | 2.2  | 0.6  | 1.6  | 8.5  |
| WPU1331 | Concrete block and brick       | 2.0  | 2.9 | 3.1 | 3.6 | 3.0  | -0.1 | 0.8  | 5.1  |
| WPU1332 | Concrete pipe                  | 2.2  | 0.5 | 2.3 | 4.1 | 2.6  | 1.3  | 5.0  | 11.2 |
| WPU1333 | Ready-mixed concrete           | 3.7  | 3.1 | 3.2 | 2.7 | 2.2  | 0.7  | 1.1  | 7.1  |
| WPU1334 | Precast concrete products      | 0.5  | 3.5 | 4.8 | 3.9 | 3.0  | 0.5  | 2.0  | 11.6 |
| WPU1335 | Prestressed concrete products  | 11.1 | 1.9 | 4.1 | 2.5 | -1.2 | 0.4  | 3.0  | 15.3 |
| WPU1342 | Brick and structural clay tile | 1.0  | 1.7 | 1.3 | 1.8 | 3.3  | 0.3  |      |      |